



GM Rubber Bumpers


Illustrations are Actual Size




11-110.....\$2.00Ea
Hood Side Bumper-Chevelle &
Camero 67-69, 66-70 Impala,
68-74 Nova




11-112.....\$4.75Ea
Seat Back Bumper With Steel Core




11-113.....\$2.25Ea
Hood Bumper-Nova 62-65




11-115.....\$2.00Ea
Hood Side Bumper-64 Chevelle, El
Camino & Impala 63-64




11-114.....\$2.25Ea
Hood Bumper-Chevy II, Nova 66-
67




11-116.....\$2.00Ea
Hood Side Bumper-Chevelle,
Impala 65




11-120.....\$2.25Ea
Door Bumper-Cutlass, Skylark,Door Bumper-Chevy II, Nova,
Chevelle 64-66



11-122.....\$2.25Ea
Door Bumper-Chevy II, Nova,
Chevelle 66-67




11-126.....\$2.00Ea
Door Bumper-Nova 68-74



4275.....\$2.00Ea
Door Bumper-GM 59




GMLICBUM.....\$1.75Ea
GM License Plate Bumper




11-137.....\$2.00Ea
62 Impala Hood Bumper




11-148.....\$2.00Ea
Glove Box Bumper 55-57, Arm
Grommet 61-64




3953CAD.....\$2.75Ea
Cadillac Front Hood Bumper



4303S.....\$2.00Ea
General Motors Door
Bumper



11-145.....\$2.00Ea
Rear Hood Bumper-Chevy 68-69



976570.....\$5.30Ea
65-70 Cadillac Hood
Bumper