



# GM Rubber Bumpers


*Illustrations are Actual Size*




11-110.....\$2.00Ea  
Hood Side Bumper-Chevelle &  
Camero 67-69, 66-70 Impala,  
68-74 Nova




11-112.....\$4.75Ea  
Seat Back Bumper With Steel Core




11-113.....\$2.25Ea  
Hood Bumper-Nova 62-65




11-115.....\$2.00Ea  
Hood Side Bumper-64 Chevelle, El  
Camino & Impala 63-64




11-114..... \$2.50 Ea  
Hood Bumper-Chevy II, Nova 66-67




11-116.....\$2.00Ea  
Hood Side Bumper-Chevelle,  
Impala 65




11-120.....\$2.25Ea  
Door Bumper-Cutlass, Skylark,Door Bumper-Chevy II, Nova,  
Chevelle 64-66



11-122.....\$2.50 Ea




11-126.....\$2.00Ea  
Door Bumper-Nova 68-74



4275..... \$2.25 Ea  
Door Bumper-GM 59




GMLICBUM.....\$1.75Ea  
GM License Plate Bumper




11-137.....\$2.00Ea  
62 Impala Hood Bumper




11-148.....\$2.00Ea  
Glove Box Bumper 55-57, Arm  
Grommet 61-64




3953CAD.....\$2.75Ea  
Cadillac Front Hood Bumper



4303S.....\$2.00Ea  
General Motors Door  
Bumper



11-145.....\$2.00Ea  
Rear Hood Bumper-Chevy 68-69



976570..... \$2.50 Ea  
65-70 Cadillac Hood  
Bumper