




Nylon Moulding Fasteners




73-3818.....\$1.50Ea
GM 73&Up




74-3978.....85Ea
Chrysler Corp. 71&Up




76-4365.....\$1.25Ea
GM 77&Up




76-4376.....\$1.25Ea
Ford Products Rocker Panel
69&Up




88-6433.....\$5.00Ea
Elcamino 78&Up
Bed Strip Clip




75-4235.....85Ea
Chrysler Products 70-76




78-4870.....85Ea
GM 1979 Back Of Rear Wheel




93326.....Discontinued
1966 Dodge Charger Rocker Panel




93328.....\$1.25Ea
1968 Impala




78-4877.....85Ea
Ford Products 1979



24019.....\$1.25Ea
70-71 GM



74-3966.....\$1.25Ea
1972-74 GM Rocker Panel



93327.....\$1.75Ea
Chrysler Corp. 'B' Body Rocker
Panel 68-70